

## ADVISORY NOTICE

06\_2023\_EC90 Bubble sensor value adjustment

Dear customer,

Due to recent change implementation, we recommend adjusting Bubble sensor limit value according to attached Technical note. This adjustment will prevent calibration issues in the future.

Applied for:

**INSTRUMENT:**

EC 90 Analyser

cat.no.INS00079

Serial numbers: from 0010-1-202005 up to 0101-1-202212

In case you have any additional question, please do not hesitate to contact us.

Best regards,



Erba Lachema s.r.o.  
Technical product management



Brno 1<sup>th</sup> March 2023

Ref.No.AN\_06\_2023

