

## ADVISORY NOTICE

27\_2022\_EC90 SW version 1.13.3

Dear customer,

We hereby inform you, that the device software of EC90 is highly recommended for update to SW version 1.13.3 issued 24<sup>th</sup> November 2022. The SW version 1.13.3 is already included from device produced from SN 4826-2-202210 onwards.

The new SW version 1.13.3 includes a new features based on additional requirements:

- Head PCB support for both (old and new PCB design)
- Rental instrument mode implemented
- Bugfixes concerning SW freeze during prime-up
- KCl prefilling error is renamed to 'Cal1 Filling'

For SW version 1.13.3, please contact your local service engineer or distributor to set up new SW version from web side [ERBA Academy](#).

Applied for:

**INSTRUMENT:**

EC 90 Analyser

cat.no.INS00079

In case you have any additional question, please do not hesitate to contact us.

Best regards,

Erba Lachema s.r.o.

Technical product management



Brno 29<sup>th</sup> November 2022

Ref.No.AN\_27\_2022

