

## ADVISORY NOTICE

02\_2024\_LAURA\_SW\_v1.17

Dear customer,

We hereby inform you that the device software of LAURA has been updated to SW version 1.17 issued on 6<sup>th</sup> February 2024.

LAURA device SW update\_v1.17 implements bug fixes:

- Bugfix: Fixes in the Russian language file

SW version 1.17 is already included in devices produced from SN 2295-1-202401 onwards.

For SW version 1.17, please contact your local service engineer or distributor to set up the new SW version from the web site [ERBA Knowledge Base](#).

Applied for:

**INSTRUMENT:**

LAURA

cat.no.INS00063

In case you have any additional questions, please do not hesitate to contact us.

Best regards,

Erba Lachema s.r.o.



Brno, February 12<sup>th</sup>, 2024

Ref. No.AN\_02\_2024